### **Traviata Accordion**

### General condition

The accordion is in a reasonable cosmetic condition externally. The bellows has been retaped at the back probably due to wear. Initally 3 of the keys were extreemly tight but have now been repaired. Most of the reed valves were curled and the instrument was very out of tune. I have used this instrument to practice tuning and replacing valves and it is now in-tune and plays reasonably well. The bass mechanism works and appears to be in good condition.

The weight of the accordion without straps is 4.5Kg.


## **Tuning**

The treble has been tuned to A=440Hz and is dry tuned. The removable bass reeds have been tuned and the fixed bass reeds await tuning.

### **Pictures**











Treble Reed Blocks



Bass Button Mechanism



Bass Reed Blocks



Bass Buttons



Bass Reed Blocks

# Summary

The instrument is a 32 bass with 41 keys from a low G to a high B. Work needed to restore it to good condition is:-

- 1. Fit new bellows gaskets to both ends.
- 2. A final tweak of the tuning